

NEW CENTRE BEARINGS

Available NOW

The range of Centre Bearings at Hardy Spicer has now been extended to include the new part numbers below. All these new parts are now available throughout the Branch Network.

Image	Part Number	Bearing ID	Bolt Hole Centres	Application
	SUB-30-8052	30mm	179mm	Subaru Outback 4Cyl (2003 - 2013)
	SUB-30-8044	30mm	169mm	Subaru Forester (2001 - 2007)
	MB-30-9223A	47mm	194mm	Mercedes Benz Sprinter (New) Front Bearing with 68.5mm centre height
	BM-30-8095	30mm	130mm	BMW X5 E53 (2000 - 2006)
	BM-30-8057	30mm	160mm	BMW 1 Series E87, X1 E84 3 Series E90/91/92/94 Aluminium Bracket (2004-2013)
	BM-30-9341	30mm	160mm	BMW X5 E70 (2007-2012) X6 E71/72 (2008-2013) Aluminium Bracket

www.hardyspicer.com.au

HSAPB-2018-0409

Ph: 1300 304 673



• HOSE • FITTINGS • DRIVESHAFTS

Central Support Group

17-31 Discovery Road, Dandenong South, 3175

Ph: (03) 9794 1900 Fax: (03) 9706 9928

ABN 52 099 707 856

Email: hspicer@hardyspicer.com.au

Web: www.hardyspicer.com.au

Branch Locations

Western Australia

Perth	49 Banksia Road, Welshpool 6106	Ph: (08) 9258 6300
Kalgoorlie	7 Keogh Way, Kalgoorlie 6430	Ph: (08) 9091 1443

South Australia

Adelaide	2/479-481 South Road, Regency Park, 5010	Ph: (08) 8349 6400
----------	--	--------------------

Victoria

Dandenong	17-31 Discovery Road, Dandenong South, 3175	Ph: (03) 9799 3250
Campbellfield	174 Fairbairn Road, Sunshine West 3020	Ph: (03) 9357 0233

Tasmania

Hobart	10 Duncan Street, Montrose 7010	Ph: (03) 6272 6907
--------	---------------------------------	--------------------

New South Wales

Sydney	37A Heathcote Road, Moorebank 2170	Ph: (02) 9600 6333
Newcastle	2 Canavan Drive, Beresfield 2322	Ph: (02) 4964 4955

Queensland

Eagle Farm	45 Harvey Street North, Eagle Farm 4009	Ph: (07) 3166 2500
Darra	12 Pradella Street, Darra 4076	Ph: (07) 3117 2800
Mackay	43 Margaret Vella Drive, Mackay 4740	Ph: (07) 4914 2100
Townsville	602 Ingham Road, Bohle 4818	Ph: (07) 4795 3400